

Release Notes for MyM Pro software version 2.1

(Outline changes and improvements done since release 1.0SR3)

Improvements and bug fixes

- Improved AGC in T tuner
- Improved stability with MPEG-4 decoding
- Uptime menu shows restart cause

New functionality

- System management/Installation overview for all units in a installation (connected to a switch) including EXM units.
- More information shown for Tuner Input (BER, Network name)
- Possibility for Enable/Disable video WD for all channels
- Output channel raster for UHF 7MHz possible
- Extended information in Service management menu

If you want more information about the new MyM Pro software release or other products, just send us an email or call us:

A2B Electronics AB, P. O. Box 14, S-591 21 Motala
Phone: +46 (0)141 229115 Fax: +46 (0)141 229101
E-mail: market@a2b.se
Web: www.a2b.se